

General Standards Corporation

8302A Whitesburg Drive, Huntsville, AL, USA 35802

Phone: (256) 880-8787

URL: www.generalstandards.com

Cage Code: 1MNS5

Product End of Life Notification

HPDI32A / HPDI32AL

General Standards Corporation is committed to providing the highest quality products and services to our customers.

As a technology developer and provider, we understand that technology evolution allows our customers to establish and maintain competitive advantages, achieve operational efficiencies, and provide superior customer service.

At General Standards Corporation, we view product EOL as a part of the life cycle that drives new technology and product innovation.

All technology products eventually reach the end of their useful life requiring a business decision to discontinue availability and maintenance.

The **HPDI32A / HPDI32AL** line of products have reached a point in its life cycle where components are increasingly difficult to source.

As such, we must make a difficult business decision to announce the EOL on the **HPDI32A / HPDI32AL** line of products effective as follows;

<u>MODEL</u>		<u>EOL Date</u>
PMC-HPDI32A	(True PMC Form Factor)	07/30/2019
PCI-HPDI32A	(True PCI Form Factor)	07/30/2019
PMC-HPDI32A-COS	(True PMC Form Factor)	07/30/2019
PCI-HPDI32A-COS	(True PCI Form Factor)	07/30/2019
PMC-HPDI32A-ASYNC*	(True PMC Form Factor)	03/30/2006
PCI-HPDI32A-ASYNCZ*	(True PCI Form Factor)	12/30/2010
PMC-HPDI32A-DIPHASE*	(True PMC Form Factor)	01/30/2008
PCI-HPDI32A-DIPHASE*	(True PCI Form Factor)	03/30/2009
PCI-HPDI32A-PRINT*	(True PCI Form Factor)	05/30/2008
PCI64-HPDI32AL	(True PCI Form Factor)	09/30/2019

We will not accept orders for any new **HPDI32A / HPDI32AL** products after **12/31/2019**

* Due to low demand, there is no replacement for the -ASYNC, -PRINT or -DIPHASE versions.

General Standards Corporation

8302A Whitesburg Drive, Huntsville, AL, USA 35802

Phone: (256) 880-8787

URL: www.generalstandards.com

Cage Code: 1MNS5

We have now completed the **PMC64-HPDI32ALT / HPDI32B**, as a replacement for the HPDI32A, HPDI32a-COS and HPDI32AL.

These boards are replacements with the same functionality and more capability; however, depending on your software driver, it is very close to a "drop in" replacement.

The following is the URL to our **PMC64-HPDI32ALT** landing page;

http://www.generalstandards.com/view-products2.php?BD_family=hpdi32alt

The following is the URL to our **PMC64-HPDI32B** landing page;

http://www.generalstandards.com/view-products2.php?BD_family=hpdi32b

We would like to suggest a free loaner board, for you and your end-users to evaluate.

For the loaner board, you can submit a PO indicating the board required as a loaner.

"Loaner" Purchase Order must state full price for whatever is ordered as well as "Bill To" and "Ship To" Information.

The loaner will be for 60 days. You will receive an invoice for the loaner items.

If the loaner is returned within 60 days, no charges will be due (full credit will be given for that invoice). If purchased, the invoice amount will be due within 60 days.

As always, we have our Technical Support team and engineers, available to assist with any questions or concerns.

General Standards Corporation understands how integral this equipment is to our customer's overall productivity. Newer technology provides more productivity and greater efficiency in the same or similar applications as these older products. As an engineering-driven company, we maintain a continuous new product development schedule.

Please contact General Standards Corporation at 1-800-653-9970 to discuss optional products or if you have any questions or concerns.

Sincerely,

General Standards Corporation